

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402195481

Date Received:
10/02/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 7 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Daniel Lapp

970-629-9525

regulatory@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699700005

Inspection Date: 09/09/2019

FIR Submit Date: 09/17/2019

FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 322392

Location Name: FEDERAL-68S104W Number: 6SWSW County: _____

Qtrqr: SWS Sec: 6 Twp: 8S Range: 104W Meridian: 6
W

Latitude: 39.391354 Longitude: -109.038624

FACILITY - API Number: 05-045- -00 Facility ID: 322392

Facility Name: FEDERAL-68S104W Number: 6SWSW

Qtrqr: SWS Sec: 6 Twp: 8S Range: 104W Meridian: 6
W

Latitude: 39.391354 Longitude: -109.038624

CORRECTIVE ACTIONS:

1 CA# 130708

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 10/17/2019

If tank is no longer in use it is considered unused equipment. Remove tank within 90 days or repair secondary containment in 30 days.

Response: CA COMPLETED

Date of Completion: 09/27/2019

Repaired berm around tank

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 130709

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 10/17/2019

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: Cleaned up dirt and compressor

COGCC Decision:

COGCC
Representative:

3 CA# 130710

Corrective Action: Comply with Rule 603.f .

Date: 12/17/2019

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: 2 seperators located west of the location do not belong to FEM, they belong to the landowner as that is private land.

COGCC Decision:

COGCC
Representative:

4 CA# 130711

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
Operator shall provide information on if the well is shut in or temporarily abandoned.

Date: 10/17/2019

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: Gas leak repiared 9/11/19

COGCC Decision:

COGCC
Representative:

5 CA# 130712

Corrective Action: Comply with Rule 603.f. (Same unused equipment on location from Inspection Doc# 675200363, 8/7/2014).

Date: 10/17/2019

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: Removed road/location drags that were written up as unused equip.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions resolved

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: HSE Manager

Date: 10/2/2019 8:00:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402195497	Federal 6-13
402195499	Federal 6-13 2
402195500	Federal 6-13 3
402195501	Federal 6-13 4

Total Attach: 4 Files