

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2019

Submitted Date:

09/30/2019

Document Number:

694900490

FIELD INSPECTION FORM

Loc ID 336023 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 950 17TH STREET, SUITE 1900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| Burger, Craig | | craig.burger@state.co.us | |
| Knudson, Dwayne | 970-456-3335 | dknudson@ursaresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 284991 | WELL | PR | 02/10/2010 | GW | 045-12337 | HANGS A2 | PR |

General Comment:COGCC Inspection Report Summary

On Monday 9/30/19 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a witness of a Braden head test at Ursa hangs A Pad, at Location # 336023 in Garfield County, Colorado.
While there, I observed Braden head bow down on API # 045-12337. Braden Head Brought discolored fluid with strong odor approximately 15-20 gallon.
This is a summary of inspection report.

Inspected Facilities

Facility ID: 284991 Type: WELL API Number: 045-12337 Status: PR Insp. Status: PR

BradenHead

Comment: 30 minute test
 Start psi Tubing=353 Casing=376 Braden Head=174
 End PSI Tubing=341 Casing=360 Braden Head=40
 brought 15-20 gallons of discolored fluid with oder.

Corrective Action: contact north engineering supervisor

Date: 10/10/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402193698 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4950953 |
| 694900499 | 694900490 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4950946 |