

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402199478

Date Received:
10/07/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611
Name of Operator: LONGS PEAK RESOURCES LLC
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Angie Galvan</u>	<u>281-734-4635</u>	<u>angie.galvan@boomtownoil.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500433
Inspection Date: 08/05/2019 FIR Submit Date: 08/09/2019 FIR Status: _____

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 418125

Location Name: LAZY D ZN Number: 03-09 County: _____
Qtrqr: NWSE Sec: 3 Twp: 11N Range: 66W Meridian: 6
Latitude: 40.949840 Longitude: -104.760390

FACILITY - API Number: 05-123-00 Facility ID: 418125

Facility Name: LAZY D ZN Number: 03-09
Qtrqr: NWSE Sec: 3 Twp: 11N Range: 66W Meridian: 6
Latitude: 40.949840 Longitude: -104.760390

CORRECTIVE ACTIONS:

1 CA# 129093

Corrective Action: 1) Operator shall provide the agreement between the Operator and the surface owner as to what seed mix was approved. If the surface owner did not have a seed mix preference, provide the consultation with the Natural Resources Conservation Service.
2) Operator shall provide the seed mix that was used to conduct Interim Reclamation activities.

Date: 08/16/2019

Please submit this information via Form 4 Sundry Notice and be sure to state somewhere on the Form 4 Sundry Notice- "Please route to Chris Binschus Reclamation Specialist".

Response: CA COMPLETED Date of Completion: 08/29/2019

Operator Comment: Surface Owner confirmed that the seed mix used on interim reclamation is agreed upon. Written confirmation provided via Sundry Form 402155563 and attached again for reference.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 129094

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices throughout the access road. Corrective action date is the date the location was observed out of compliance.

Date: 08/05/2019

See COGCC Comments section for additional corrective action compliance.

Response: CA COMPLETED

Date of Completion: 09/05/2019

Operator Comment: BMP's have been installed and the access road has been repaired. The invoice from the contractor is attached.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Angie Galvan

Signed: _____

Title: Regulatory

Date: 10/7/2019 11:03:17 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402199509	Invoice
402201256	Seed Confirmation

Total Attach: 2 Files