

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402201396

Date Received:
10/07/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611
Name of Operator: LONGS PEAK RESOURCES LLC
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Angie Galvan</u>	<u>2817344635</u>	<u>angie.galvan@boomtownoil.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500440
Inspection Date: 08/05/2019 FIR Submit Date: 08/09/2019 FIR Status: _____

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 438066

Location Name: Railay West Number: 2833-1NH County: _____
Qtrqtr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.985330 Longitude: -104.784320

FACILITY - API Number: 05-123-00 Facility ID: 438066

Facility Name: Railay West Number: 2833-1NH
Qtrqtr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.985330 Longitude: -104.784320

CORRECTIVE ACTIONS:

1 CA# 129096

Corrective Action: 1) Operator shall provide the agreement between the Operator and the surface owner as to what seed mix was approved. If the surface owner did not have a seed mix preference, provide the consultation with the Natural Resources Conservation Service.
2) Operator shall provide the seed mix that was used to conduct Interim Reclamation activities.
Please submit this information via Form 4 Sundry Notice and be sure to state somewhere on the Form 4 Sundry Notice- "Please route to Chris Binschus Reclamation Specialist" by August 16, 2019.
3) Operator shall control and manage all noxious weeds. Corrective action date is the date the location was observed out of compliance, August 5, 2019.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 08/26/2019

Operator Comment: Surface Owner confirmed the seed mix used on the original interim reclamation. Written confirmation was submitted and approved via Sundry Form 4021553661.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 129097

Corrective Action: Comply with Rule 1004. Corrective action date is the date the location was observed out of compliance, August 5, 2019.
See COGCC Comments section for additional corrective action compliance.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 09/30/2019

Operator Comment: Form 19 Supplement Report document number 402178786 and the closure request has been approved and it is noted that no further action is necessary at this time.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 129098

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance.
See COGCC Comments section for additional corrective action compliance.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 08/18/2019

Operator Comment: Berms were compacted and BMP's on pad were corrected. Miller HFI contractors completed the work, the invoice is attached for reference.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Angie Galvan

Signed: _____

Title: Regulatory

Date: 10/7/2019 12:08:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402201408	Invoice
-----------	---------

Total Attach: 1 Files