

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2019

Submitted Date:

10/08/2019

Document Number:

699700009**FIELD INSPECTION FORM**Loc ID 322388 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		regulatory@foundationenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210397	WELL	PR	01/06/2003	GW	045-06153	FEDERAL 1-15	EI
467553	SPILL OR RELEASE	AC			-	1-15 Vertical Separator	EI

**General Comment:**

On September 10, 2019, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of FOUNDATION ENERGY MANAGEMENT LLC (Foundation, operator# 10112) Location ID 322388 to examine Pit ID 112128, 112129 and 112130. Weather was partly sunny and temperatures about 70 degrees Fahrenheit.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Sign not posted on tanks or containers (HR Brand stock tanks, see photos)		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	11/08/2019

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			
Condensate	Separator	<= 1 bbl			
Comment:	COGCC staff observed an area of stained soil beneath the vertical separator. Operator was contacted via email on 9/13/2019 to submit an F19 Spill/Release Report (See photos).				
Corrective Action:					Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	210397	Type:	WELL	API Number: 045-06153	Status: PR	Insp. Status: EI
Facility ID:	467553	Type:	SPILL OR	API Number: -	Status: AC	Insp. Status: EI

**Environmental****Spill/Remediation:**

Comment:	<p>COGCC staff observed a total of three pits on location (See photos).</p> <p>1. West of the wellhead, measuring 20 feet by 20 feet by 5 feet deep. No hydrocarbon staining present.</p> <p>2. North of the horizontal heated separator, measuring 15 feet by 15 feet by 2 feet deep. Hydrocarbon staining was observed in pit bottom.</p> <p>3. East of vertical separator, measuring 10 feet by 10 feet by 3 feet deep. Hydrocarbon staining was observed in pit bottom.</p> <p>COGCC staff observed soil sample locations in each one of the three pits on the sidewalls on pit bottoms.</p> <p>COGCC database and records indicate three pits associated with the location, 112128, 112129, and 112130.</p>	
Corrective Action:	<p>Operator shall submit and update to Remediation Project 11304, Doc# 401625018 with the correct lat/long for the pits on location.</p> <p>Operator shall update the Multiple Facilities tap to address Doc# 401628371 (Soil Sample Location Map) which indicates that three pits were sampled under Remediation Project 11304.</p>	Date: 11/23/2019

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700038	20190910 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957897">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957897</a>