

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402208825

Date Received:  
10/14/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Randy Madison

Phone

575-445-6706

Email

rmadison@wapitienergy.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 689901301

Inspection Date: 09/25/2019

FIR Submit Date: 09/25/2019

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: ARP PRODUCTION COMPANY LLC

Company Number: 10471

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

**LOCATION - Location ID: 308367**

Location Name: VPC C-635S67W Number: 11NESE County: LAS ANIMAS

Qtrqtr: NESE Sec: 11 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.008650 Longitude: -104.851610

**FACILITY - API Number: 05-071- -00 Facility ID: 269528**

Facility Name: VPC C Number: 121

Qtrqtr: NESE Sec: 11 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.008650 Longitude: -104.851610

**CORRECTIVE ACTIONS:**

**1** CA# 131070

Corrective Action: Comply with Rule 1003.f.  
Control noxious weeds.

Date: 07/11/2019

Response: CA COMPLETED

Date of Completion: 10/07/2019

Operator  
Comment:

The noxious weeds on the slope have been cut, bagged and disposed of properly. The area has been seeded. The area will continue to be monitored and if it needs reseeded in the spring of 2020 it will be seeded again. Note: consulted a reclamation specialist that is reclaiming the mine located on VPR. He has advised me that it can take 2 to 3 years to reestablish vegetation on those slopes in that soil. They have been reclaiming that mine for 20 plus years.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 131071

Corrective Action: Comply with the 1003 interim reclamation rules.  
Stabilize the cut slope.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 10/14/2019

Operator  
Comment: The culverts are cleaned out and the area at the end of the culvert will have rock installed. That is a natural  
raven that is at the end of that culvert and doing more than adding rock would do more damage than good.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The weeds have been removed from this location. The area is turning a little green from the seed that was planted, however it has been freezing at night in this area. We will monitor the growth come the spring of 2020 and reseed if needed. Herbicides will be applied in the spring to control weed growth per the weed plan.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison

Signed: \_\_\_\_\_

Title: HSE Specialist

Date: 10/14/2019 1:56:33 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402208843	Weed Remediation C-121 Photo 1
402208844	Weed Remediation C-121 Photo 2
402208847	Weed Remediation C-121 Photo 3

Total Attach: 3 Files