

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401941427

Date Received:

02/15/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Amato, Joseph</u>	<u>719-845-2110/719-859-2263</u>	<u>josephamato@tcenergy.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695100006
Inspection Date: 01/16/2019 FIR Submit Date: 01/16/2019 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 309367

Location Name: HILL RANCH EAST-634S67W Number: 23SWNE County: LAS ANIMAS
Qtrqr: SWNE Sec: 23 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.073196 Longitude: -104.856891

FACILITY - API Number: 05-071-00 Facility ID: 293796

Facility Name: HILL RANCH EAST Number: 23-07
Qtrqr: SWNE Sec: 23 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.073196 Longitude: -104.856891

CORRECTIVE ACTIONS:

1 CA# 121768

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/18/2019

Response: CA COMPLETED Date of Completion: 01/18/2019

Operator Comment: Packing has been repaired.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 121769

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 02/16/2019

Response: CA COMPLETED

Date of Completion: 02/11/2019

Operator
Comment:

The soil below the drive head has been cleaned and removed from the location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Packing has been repaired and the soil has been cleaned from the location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joseph Amato

Signed: _____

Title: Regulatory Manager

Date: 2/15/2019 10:04:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401941427	FIR RESOLUTION SUBMITTED
401941494	Location Photo

Total Attach: 2 Files