

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402229365

Date Received:

11/01/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10639

Name of Operator: CPX PICEANCE HOLDINGS LLC

Address: 34 S WYNDEN DR STE 240

City: HOUSTON State: TX Zip: 77056

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kurtenbach, Nick

nick@cpxpiceance.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692401375

Inspection Date: 09/23/2019

FIR Submit Date: 09/29/2019

FIR Status: _____

Inspected Operator Information:

Company Name: CPX PICEANCE HOLDINGS LLC

Company Number: 10639

Address: 34 S WYNDEN DR STE 240

City: HOUSTON State: TX Zip: 77056

LOCATION - Location ID: 334460

Location Name: TPR Well Pad Number: 36A County: _____

Qtrqr: SWNE Sec: 36 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.395017 Longitude: -107.831908

FACILITY - API Number: 05-045- -00 Facility ID: 334460

Facility Name: TPR Well Pad Number: 36A

Qtrqr: SWNE Sec: 36 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.395017 Longitude: -107.831908

CORRECTIVE ACTIONS:

3 CA# 131244

Corrective Action: CA#1) If the Operator does not drill additional wells; perform reclamation in accordance with Interim Reclamation Rule 1003. Reclamation Activities to be complete by 6/15/20.

Date: 11/01/2019

OR:

CA#2) Operator shall submit a Variance Request via Form 4 Sundry for compliance with additional bonding requirements as identified in the Notice to Operators: for Interim Reclamation Procedures for Delayed Operations (January 5, 2017) by 11/1/19.

Regardless of CA responded to; Reclamation must be completed at area of former pit and tank battery to NW of main Pad. Reclamation Activities to be complete by 6/15/20.

Response: CA COMPLETED

Date of Completion: 11/01/2019

Operator Comment: Reclamation Variance Request Form 4 Doc#402227864

COGCC Decision: _____

COGCC Representative: _____

4 CA# 131245

Corrective Action: Install or repair required BMPs per Rule 1002.f, incorporating with slope stabilization
Install BMPs @ Stockpile of unidentified material at southwest corner of pad. Loose Piles of material are potential Pollution sources and need to be stabilized.

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 10/24/2019

Operator Comment: Removed stockpiled material rather than installing BMPs, repaired cutslope where undermining of root systems was occurring. See attached photos.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Attention: Lou Colby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kent Rider

Signed: _____

Title: Regulatory Consultant

Date: 11/1/2019 4:27:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402229382	Photo
402229383	Photo

Total Attach: 2 Files