

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2019

Submitted Date:

11/06/2019

Document Number:

687905810

**FIELD INSPECTION FORM**Loc ID 313569 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224508	WELL	PR	03/06/2018	GW	083-06573	SAND CANYON 9	PR

**General Comment:**[Site inspection and equipment inventory with photos at the end of this report.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel access road.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign at entrance to location has been damaged by bullet holes and unlegible.		
Corrective Action:	Replace sign per Rule 210.	Date:	12/06/2019

Emergency Contact Number:			
Comment:	Company contact information is current. Missing local area emergency contact information or "911" on location sign. See photo.		
Corrective Action:	Update sign to include local emergency contact or "911" per Rule 210.		Date: 12/06/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead with dual block valve assembly installed.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	1-6" SS flowline from wellhead to offsite gathering system.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 224508	Type: WELL	API Number: 083-06573	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Stormwater BMP's appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905811	Sign damaged and missing emergency contact information.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982511">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982511</a>
687905812	Overview photo looking North.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982512</a>