

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/07/2019

Submitted Date:

11/07/2019

Document Number:

679601870**FIELD INSPECTION FORM**
 Loc ID 302376 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		wellinspections@bayswater.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298335	WELL	PR	05/06/2019	OW	123-29035	LIND 20-14	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris in wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	11/14/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 298335 Type: WELL API Number: 123-29035 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment

User

Date

THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 696300045. All corrective actions assigned in previous inspection DOC#: 696300045 have been resolved. ONE (1) NEW CORRECTIVE ACTION HAS BEEN ASSIGNED TO THIS LOCATION. PLEASE REVIEW MY INSPECTION SUMMARY REPORT, PHOTOS AND PREVIOUS INSPECTION DOC#: 696300045 FOR ADDITIONAL INFORMATION ON THIS LOCATION.

santistb

11/07/2019

COGCC Inspection Report Summary

On Thursday, November 7, 2019 at approximately 13:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at LIND 20-14 (Bayswater Exploration & Production), at location #: 302376 in WELD COUNTY Colorado.

While there, I observed a shut in wellhead.

During this inspection the following possible compliance issues were observed:

1. Debris within wellhead fencing. Please remove and COMPLY WITH RULE 603.F. (Corrective Action Date: November 14, 2019) See attached photo #2.

Form 10 DOC#: 402197499 (IN PROCESS) is in well file.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Continuing Education Inspection

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601871	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983457