

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/08/2019

Submitted Date:

11/09/2019

Document Number:

679706004

**FIELD INSPECTION FORM**

Loc ID 314500 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 100 CHEVRON USA INC  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Sanford, Anita		atlx@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228864	WELL	PR	12/01/2017	OW	103-05855	WILSON CREEK UNIT 57	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 11-8-2019 at approximately 12:40, inspector Rick Moran, conducted a routine inspection at Chevron well Wilson Creek Unit 57 in Rio Blanco county.

The following compliance issues were observed:

- 1) Missing 911 on location sign. Photo 2. Complete by 12-8-2019.
- 2) Two borken deadman markers. Photo 3. Complete by 12-8-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 67970.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on location sign.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/08/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Ancillary equipment	# 1		
Comment:	<span style="color: blue;">Container of RE9306WCW with secondary containment.</span>		
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	<span style="color: blue;">Two broken deadman markers.</span>		
Corrective Action:	<span style="color: red;">Install proper guy line markers per Rule 1003.a</span>	Date:	<u>12/08/2019</u>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 228864 Type: WELL API Number: 103-05855 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706005	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984680">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984680</a>