

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/08/2019

Submitted Date:

11/09/2019

Document Number:

679706012

FIELD INSPECTION FORM

Loc ID 314515 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 100 CHEVRON USA INC
City: RANGELY State: CO Zip: 81648

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita		atlx@chevron.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228892	WELL	PR	12/01/2017	GW	103-05888	WILSON CREEK UNIT 18	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 11-8-2019 at approximately 14:00, inspector Rick Moran, conducted a routine inspection at Chevron well Wilson Creek Unit 18 in Rio Blanco county.

The following compliance issues were observed:

- 1) Missing 911 on location sign. Photo 2. Complete by 12-8-2019.
- 2) Two fallen deadman markers. Photo 3. Complete by 12-8-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706012.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on location sign.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/08/2019

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Two fallen deadman markers.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	<u>12/08/2019</u>
Type: Ancillary equipment	# 1		
Comment:	One container if RE9306WCW with secondary containment.		
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 228892 Type: WELL API Number: 103-05888 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706013	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984702