

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/13/2019

Submitted Date:

11/13/2019

Document Number:

693501713

FIELD INSPECTION FORM

Loc ID 451044 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451033	WELL	DG	04/02/2019		123-44938	Regnier Farms 1C-19H-B268	DG

General Comment:

Inspected FacilitiesFacility ID: 451033 Type: WELL API Number: 123-44938 Status: DG Insp. Status: DG**Complaint**

Comment: [Inspection in response to complaint.](#)
[Field Inspector Assigned: Randy Silver](#)
[Complaint Received](#)
[Date: 11-11-2019](#)
[Complaint Contacted:](#)
[Date: 11-13-2019 Time:](#)
[Location ID # 451044](#)
[Location Name: Regnier Farms](#)
[Inspection Document # 693501711](#)
[Complaint Document # 200448280](#)
[Nature of Complaint: Noise](#)
[Field Inspector Actions:](#)
 On 11-11-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Rod Brueske stated the issues were occurring outside of complainants home.
 On 11-13-2019, I attempted to make contact with the complainant who indicated that on 11-09-19 he experienced noise all night into the morning.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual noise in or around location. Myself and my supervisor Jason Gomez set up COGCC sound study equipment 350ft to the west of location. Detailed information and photos in FIR inspection doc#693501711. This will be a four-day study. Third party sound study information will be attached to complaint inspection FIR doc.
 At time of inspection, I spoke with one of the fracing supervisors and he stated at time of complaint they were fracing and no unusual activity was taking place.
 Weather conditions: clear and location wet in spots
 See inspection document #693501711 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See Doc#693501711 for full inspection. Third pary sound study is attached.	silverr	11/13/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501714	Sound study 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987140
693501715	Sound study 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987141
693501716	Sound study 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987142
693501717	Sound study 4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987143
693501718	Sound study 5	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987144
693501720	Sound study 6	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987145