

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Comply with rule 907.e	Date:	06/02/2019
Type	DEBRIS		
Comment:	Dead weeds around wellsite		
Corrective Action:	Comply with Rule 603.f	Date:	05/16/2019

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:	Does not appear to be plumbed to surface			
Corrective Action:			Date:	
Ancillary equipment		# 1		
Comment:	Electric panel, transformers and meter box			
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241700 Type: WELL API Number: 123-09489 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 10/13/19 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Elkhorn Company B #7 KP Kauffman, at API #05-123-09489 in Weld County Colorado. While there, I observed Producing Wellsite. This is a follow up inspection per Docs. # 688402086 and 699300241. During this inspection the following possible compliance issues were observed: Stained soil: Rule 907.e this Compliance issue is delinquent per Doc. # 688402086 and 699300241 CA date 6/2/2019 See photo #4. Debris/weeds: Rule 603.f It appears that the dead weeds around location have not been addressed creating compliance issue to be delinquent CA date 5/16/2019 See attached photo #3. Submitting inspection to enforcement due to compliance issues not being addressed Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	11/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300555	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4988071