



00215542



Dakota Energy and Resources, Inc.

OIL AND GAS PRODUCERS

P.O. BOX 440
I-90 & DEADWOOD AVENUE
RAPID CITY, SD 57709
(605) 342-7224

PETER C. LIEN, President
CHARLES H. LIEN, Chairman of the Board
BRUCE H. LIEN, Vice President
DOUGLAS R. SORENSEN, Secretary-Treasurer

May 24, 1993

RECEIVED

MAY 27 1993

COLO. OIL & GAS CONSERV. COM.

Colorado Oil & Gas Conservation Commission
Suite 380, 1580 Logan Street
Denver, CO 80203

Attention: Well Records

Re: Lindvall #11-10
NE SW 10-7N-60W
Weld County, Colorado

To Whom It May Concern:

Enclosed are copies of two bills Dakota Energy & Resources, Inc. paid on the above referenced well after the well had been inspected for plugging and abandonment.

Should you have any questions, please contact our office.

Thank you.

Sincerely,

Dot Rasmusson

Encls.

0126752

GSCC-652-3

TOTAL BULK 22
TOTAL PLS# 16.95



**CASTERLINE
SEEDS
CASTERLINE & SONS
SEEDS, INC.**

First & Maple
P. O. Box 1377
316-225-4137

Dodge City, Kansas 67801

LIMITATION OF WARRANTY AND LIABILITY

CEASESTARLINE AND DEALER warrant that this seed is as described on this bag and the bag to which it is attached, within any recognized tolerance. **CEASESTARLINE AND DEALER** MAKE NO OTHER REPRESENTATION **WARRANTY** OF ANY KIND, EXPRESS OR IMPLIED, AS TO MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY OTHER MATTER WITH RESPECT TO THIS SEED and, except where expressly prohibited, specifically disclaim any and all loss of yield due in any cause, including environmental conditions, diseases, insects, soil conditions, chemicals, farming practices or the reasons of this seed, arising under any such conditions. **PURCHASER'S EXCLUSIVE REMEDY** SHALL BE FOR DAMAGES AND COSTS OF LITIGATION IN CONNECTION WITH **CEASESTARLINE** AND ITS DEALER FOR ANY AND ALL LOSSES AND DAMAGES ARISING FROM ANY CAUSE WHATSOEVER (WHETHER SUCH CAUSE BE BASED IN CONTRACT, NEGLIGENCE, STRICT LIABILITY, OTHER TORT OR OTHERWISE) SHALL IN NO EVENT EXCEED THE PURCHASE PRICE OF THE SEED IN RESPECT TO WHICH SUCH CAUSE ARISES OR, AT **CEASESTARLINE'S** OPTION, REPLACEMENT OF SUCH SEED; AND IN NO EVENT SHALL **CEASESTARLINE** OR ITS DEALER BE LIABLE FOR INCIDENTAL, CONSEQUENTIAL OR PUNITIVE DAMAGES RESULTING FROM ANY SUCH CAUSES. All claims for any cause whatsoever (whether such cause be

DAKOTA ENERGY
AND RESOURCES, INC.
P.O. BOX 410 PH. 605-342-7224
RAPID CITY, SD 57709

First Bank Rapid City
Member FDIC
First Bank of South Dakota (National Association)
P.O. Box 53
Rapid City, SD 57709

1157

78-45/914

October 11 1990

PAY Nine Hundred Ninety and no/100----- DOLLARS \$990.00

TO
THE
Gear Drilling Company
518 Seventeenth Street
Suite 470 Denver Club Building
Denver, CO 80202

DAKOTA ENERGY AND RESOURCES, INC.

NOT NEGOTIABLE

⑈001157⑈ ⑆091400157⑆ ⑆1404557⑆

DAK. ENERGY & RESOURCES, INC.


DELUXE - FORM WVC-3 SPL

DATE	INVOICE NUMBER	DESCRIPTION	AMOUNT	DISCOUNTS OR DEDUCTIONS	NET AMOUNT
10/2/90	24-3008-2	Lindvall 11-10 - Excess dirt Work			\$990.00
<i>Handwritten note:</i> Note - This invoice is for the amount owed by Lindvall to us. It is not to be paid out.					

62-571-1824-4-5000AB

Received 10-5-90

? Kite ✓
Sam ✓
Dany ✓
Dot —



GEAR DRILLING COMPANY
518 SEVENTEENTH STREET
SUITE 470 DENVER CLUB BUILDING
DENVER, COLORADO 80202

(303) 623-4422
(303) 623-2283

GEORGE L. GEAR, PRESIDENT

I N V O I C E

TO: DAKOTA ENERGY AND RESOURCES, INC.
P.O. Box #440
Rapid City, South Dakota 57705

INVOICE NO.: 24-3008-2

DATE: October 2ne, 1990

To bill you for the excess dirt work in connection with the drilling of your LINDVALL NO.11-10, NE SW of Section 10, Township 7 North, Range 60 West, Weld County, Colorado, as per our Drilling Contract dated April 6th, 1990:

PCL ✓

Bob's Dozer Service inv.#8873

\$990.00

TOTAL INVOICE AMOUNT: \$990.00

(contract allowance for dirt work has been satisfied)

" THANK YOU "

76 3008

Bob's
DOZER SERVICE

PHONE 522-1186 OR 522-0051

OIL FIELD EXCAVATING AND DIRT CONTRACTING

1304 N. 6TH ST. - STERLING, COLORADO 80751

Invoice No. 8873

In account with:

Gear Drilling Co.

Denver, Colo.

Dakota

9/26, 1990

Authorized by Marty Gieger

Location LINDVALL 1110

Rig 2

Date Work Performed 7/24 - 9/18

Service Rendered as Follows:

Travel time - Backfilled reserve pit.
Dozed location back to original grade.
Dozed mud out of reserve & left to dry.
Dozed back into reserve & covered with dirt.

Dozer & Operator

Hours

Rate

Amount

18

55.00

\$990.00

DEDUCT 2% IF PAID IN 30 DAYS

DAKOTA ENERGY
AND RESOURCES, INC.
P.O. BOX 470 PH. 605 342-7221
RAPID CITY, SD 57709

South Dakota
P.O. Box 470
Rapid City, SD 57709

1441

May 24 91

78-45/914

Five Hundred Fifty and no/100-----DOLLARS \$550.00

Thomas Dale Green
55500 W.C. RD 86
New Raymer, CO 80742

DAKOTA ENERGY AND RESOURCES, INC.

NOT NEGOTIABLE

NO. 1441# 1091400457# 11001557#

DAK. ENERGY & RESOURCES, INC.

DELUXE - FORM YVVO-3 SPL

DATE	INVOICE NUMBER	DESCRIPTION	AMOUNT	DISCOUNTS OR DEDUCTIONS	NET AMOUNT
4/29/91	126752	Lindvall No.1			\$550.00

C2-37L M234 4-3000AD