

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/13/2019

Submitted Date:

11/13/2019

Document Number:

697600586

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: GINTAUTAS, PETER On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	(303) 825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>
		MKnop@kpk.com	
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
468756	SPILL OR RELEASE	AC	10/25/2019		-	Nessu 1	EI

**General Comment:**

[flowline related spill not on location](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			
Crude Oil	Gathering Line	>= 5 bbls			
Comment: <a href="#">see attached photos of current excavation spill 468756 reported with first supplemental 19 received.</a>					
Corrective Action: <a href="#">submit form 27 for prior approval before conducting any ChemOx or other on site remediations of impacted soils. Excavation, haul and dispose of impacted soils at landfill may continue without submission of site investigation and remediation plan</a>				Date:	<u>11/14/2019</u>

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 468756 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [no berms or other BMPs in place to minimize runoff of soils from excavation see attached photos](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 11/14/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402238576	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987506</a>
697600587	excavated soils	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987496</a>
697600588	excavation of spill	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987497">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987497</a>