

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/20/2019

Document Number:

693501799**FIELD INSPECTION FORM**Loc ID 451044 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451033	WELL	DG	04/02/2019		123-44938	Regnier Farms 1C-19H-B268	DG

General Comment:

Inspected Facilities

Facility ID: 451033 Type: WELL API Number: 123-44938 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 11-17-2019
 Complaint Contacted:
 Date: 11-19-2019 Time: 8:41AM via phone left voice mail
 Location ID #451044
 Location name: Regnier Farms
 Inspection Document # 693501790
 Complaint Document #200448316
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 11-17-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Amanda Harper 517 County Road 18 Longmont CO stated the issues were occurring outside of complainants home.
 On 11-19-2019, I attempted to make contact with the complainant who indicated that on 11-12-19 she was woken by a loud grinding jet engine sound from Regnier well site during the Flow back phase. She also stated the violated the sound rule for sound over a certain decibel stopping after 10 min.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not smell any unusual Noise. Regnier farms is currently in the fracing stage not Flow back. Sound rule states (noise levels may be increased ten (10) dB (A) for a period not to exceed fifteen (15) minutes in any one (1) hour period). Third party sound study information is attached to complaint inspection.
 At time of inspection, I spoke with fracing supervisor he stated at time of complaint they were fracing and no unusual activity was taking place. Also after speaking with supervisors, one crew rigged out on 11-17-19, 2nd crew should be done on 11-20-19 and last crew should be completed on 11-24-19 if ever thing goes as scheduled.
 Weather conditions: Cloudy and location dry
 See inspection document #693501790 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See Doc#693501790 for full inspection. Third party sound study is attached.	silverr	11/20/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501800	Sound 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993072
693501801	Sound 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993073
693501802	Sound 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993074
693501803	Sound 4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993075