

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Wrong sign to wellhead. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/21/2019

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment inside wellhead fencing. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	11/28/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 271721 Type: WELL API Number: 123-22105 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>**Weather Conditions: wet, some snow.</p> <p>COGCC Inspection Report Summary On Thursday, November 21, 2019 at approximately 10:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at WILLIAMS I 34-13X (Noble Energy), at location #: 332296 in WELD COUNTY Colorado. While there, I observed a temporarily abandoned wellhead. During this inspection the following possible compliance issues were observed: 1. Wrong sign at wellhead. INSTALL SIGN TO COMPLY WITH RULE 210.B. (Corrective Action Date: December 21, 2019) See attached photo #1. 2. Unused equipment inside fencing that contains wellhead. COMPLY WITH RULE 603.F. (Corrective Action Date: November 28, 2019) See attached photo #3,4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	11/21/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601944	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994778