

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402248372

Date Received:

11/25/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69805

Name of Operator: PETROX RESOURCES INC

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Nystrom, Dusty

nystrow@yahoo.com

Clark, Ryan

303-803-3998

Ryan@petrox-resources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900918

Inspection Date: 10/08/2019

FIR Submit Date: 10/15/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PETROX RESOURCES INC

Company Number: 69805

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

LOCATION - Location ID: 320887

Location Name: CANDELARIA 10U-M34N5W Number: 10SWSW County: ARCHULETA

Qtrqr: SWS Sec: 10 Twp: 34N Range: 5W Meridian: M  
W

Latitude: 37.201690 Longitude: -107.386520

FACILITY - API Number: 05-007-00 Facility ID: 279975

Facility Name: CANDELARIA 33-5 FEE Number: 10U #3

Qtrqr: SWS Sec: 10 Twp: 34N Range: 5W Meridian: M  
W

Latitude: 37.201690 Longitude: -107.386520

CORRECTIVE ACTIONS:

1 CA# 131649

Corrective Action: Control weeds immediately. Corrective action date will remain to document time out of compliance. Interim reclamation areas need revegetation after weed control during the fall 2019 seeding window and no later than 11/15/2019. Mulching and livestock exclusion appear needed for successful revegetation.

Date: 06/01/2019

Response: CA COMPLETED

Date of Completion: 11/07/2019

Weeds were spot sprayed on 10/7/2019 and location was bladed. On 11/14/2019 the north hillside was seeded.

Operator Comment: On 11/18/2019 erosion control was added on the north hillside and the location was fenced. Pictures are attached.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

2 CA# 131650

Corrective Action: Oil leaking from barrel should be cleaned as of the day of notification on 10/9/2019. Stand needs to be secured to prevent future tipping and spills. A followup inspection will be conducted to verify proper cleanup and removal of contaminated material, as well as proper anchoring of oil drum stand.

Date: 10/22/2019

Response: CA COMPLETED

Date of Completion: 10/10/2019

Operator Comment: Oil barrel was resecured and oil was removed and disposed of.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: In the future can Petrox FIRs be submitted to Ryan Clark: Ryan@Petrox-Resources.com

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Clark

Signed: \_\_\_\_\_

Title: Engineer

Date: 11/25/2019 1:51:07 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402248399	Photos
-----------	--------

Total Attach: 1 Files