

STATE OF COLORADO  
OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY

Received  
11-10-97  
JA



SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

FOR OFFICE USE ONLY			
ET	FE	UC	SE

3 FEDERAL INDIAN OR STATE LEASE NO. Free

6 PERMIT NO. \_\_\_\_\_

7 API NO. 05-057-6244

8 WELL NAME #1 South Coalmont

9 WELL NUMBER #1

10 FIELD OR WILDCAT Wildcat

11 QTR. QTR. SEC., T.R. AND MERIDIAN See 6, T6N, R80W

12 COUNTY Jackson

1 OIL WELL  GAS WELL  COALBED METHANE  INJECTION WELL  OTHER

2 NAME OF OPERATOR Joe Doyle

3 ADDRESS OF OPERATOR \_\_\_\_\_

CITY \_\_\_\_\_ STATE \_\_\_\_\_ ZIP CODE \_\_\_\_\_

4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface 3925' FNL 1730' FWL  
At proposed prod zone NE SW Sec 6, T6N, R80W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER \_\_\_\_\_

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
- ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS)
- REPAIRED WELL
- OTHER \_\_\_\_\_

\*Use Form 5 - Well Completion or Recompletion Report and Log for subsequent report of Multiple/Commingled Completions and Recompletions

13C. NOTIFICATION OF:

- SHUT-IN, TEMPORARILY ABANDONED (DATE \_\_\_\_\_) (REQUIRED EVERY 6 MONTHS)
- PRODUCTION RESUMED (DATE \_\_\_\_\_)
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER \_\_\_\_\_

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK Proposed for Nov. 97

1. Set CIBP 50' above Shannon perf 5074'-5084' w/2 sk cement on top CIBP.
2. Perf 5 1/2" casing at 680' & squeeze 100' plug in & out of 5 1/2" & across 9 5/8" casing shoe at 630'.
3. Spot 30' plug at surface in & out of 5 1/2" casing.
4. Cut head off 4' below GL & weld on plate w/well info.

16. I hereby certify that the foregoing is true and correct

SIGNED William J. Rippy Jr.

NAME (PRINT) BILL RIPPY

TITLE Contractor (Agent)

TELEPHONE NO. 970-858-3736

DATE 11/10/97

(This space for Federal or State office use)

APPROVED [Signature]  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

NORTHWEST AREA ENGINEER

TITLE \_\_\_\_\_

DATE 11-10-97