

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402252380

Date Received:  
12/03/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 693900803  
Inspection Date: 09/16/2019 FIR Submit Date: 09/20/2019 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

### LOCATION - Location ID: 413695

Location Name: TIFFANY 32-7 12 Number: 4 County: LA PLATA  
Qtrqr: NWNE Sec: 12 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.037540 Longitude: -107.558500

### FACILITY - API Number: 05-067- -00 Facility ID: 412181

Facility Name: TIFFANY 32-7 12 Number: 7  
Qtrqr: NWNE Sec: 12 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.037540 Longitude: -107.558500

### CORRECTIVE ACTIONS:

1 CA# 130895

Corrective Action: Reclamation/revegetation needs to be conducted within portions of the project area that are not in use for production operations. Cattle exclusion may be needed for vegetation establishment.

Date: 11/15/2019

Response: CA COMPLETED Date of Completion: 12/03/2019

Operator Comment: Landowner does not want area reseeded.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 130896

Corrective Action: Install erosion controls such as mulching on revegetation areas, and sediment controls to stabilize bare soils and prevent sediment discharge until vegetation is established and location is stabilized. This should be conducted in coordination with revegetation described above.

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 12/03/2019

Operator  
Comment:

Landowner does not want area reseeded or the erosion controls installed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: PRISCILLA SHORTY

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 12/3/2019 2:14:11 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files