

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402256021

Date Received:
12/05/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Distribution, Evergreen

cogcc.evergreen@enrllc.com

Tom Beardslee

tom.beardslee@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 695101333

Inspection Date: 09/12/2019

FIR Submit Date: 09/12/2019

FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307835

Location Name: COLOROW-634S65W Number: 24NENW County: LAS ANIMAS

Qtrqtr: NENW Sec: 24 Twp: 34S Range: 65W Meridian: 6

Latitude: 37.074700 Longitude: -104.624110

FACILITY - API Number: 05-071- -00 Facility ID: 257733

Facility Name: COLOROW Number: 21-24

Qtrqtr: NENW Sec: 24 Twp: 34S Range: 65W Meridian: 6

Latitude: 37.074700 Longitude: -104.624110

CORRECTIVE ACTIONS:

1 CA# 130536

Corrective Action: REMOVE UNUDED EQUIPMENT, COMPLY WITH RULE 603.f.

Date: 10/12/2019

Response: CA COMPLETED

Date of Completion: 09/13/2019

Operator Comment: Removed unused equipment to comply with Rule 603.f.

COGCC Decision: _____

COGCC
Representative:

2 CA# 130537

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 10/12/2019

Response: CA COMPLETED

Date of Completion: 09/13/2019

Operator
Comment:

Installed proper guy line markers per Rule 1003.a.

COGCC Decision: _____

COGCC
Representative:

3 CA# 130539

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 902.b.

Date: 10/12/2019

Response: CA COMPLETED

Date of Completion: 09/13/2019

Operator
Comment:

Lowered fluid level so at least two feet of freeboard exist, per Rule 902.b.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: No photos of the CA are available currently

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cheri Morgan

Signed: _____

Title: Regulatory Specialist

Date: 12/5/2019 6:24:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files