

FORM
INSPRev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2019

Submitted Date:

12/12/2019

Document Number:

693501951

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
455317 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455304	WELL	DG	06/07/2019		014-20746	Livingston S19-25-9N	DG

General Comment:

Inspected FacilitiesFacility ID: 455304 Type: WELL API Number: 014-20746 Status: DG Insp. Status: DG**Complaint**

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 12-6-2019
 Complaint Contacted:
 Date: 12-9-2019 Time: 3:09PM via phone
 Location ID #455317
 Location name: Livingston
 Inspection Document # 693501869
 Complaint Document #200448388
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 12-06-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Tammy Raichle 3395 Yale Drive Broomfield CO stated the issues were occurring outside of complainants home.
 On 12-9-19-2019, I attempted to make contact with the complainant who indicated that on 12-05-19 she experienced a loud noise coming from the fracking site near her. It sounds like a humming engine. It gets louder and louder then slowly fades away then repeats. I explained the fracing process to her.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual noise in or around location. After reviewing third party sound study data, location is with in compliance per COGCC rules. Sound study data will be attached to compliant inspection form.
 At time of inspection, I spoke with fracing supervisor he stated at time of complaint they were fracing and no unusual activity was taking place. This is Liberty Oil Field Services Tier 4 Quiet fleet.
 Weather conditions: Raining
 See inspection document #693501869 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See Doc # 693501869 for full inspection. Third party sound study is attached to complaint inspection.	silverr	12/12/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501952	Sound study 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011262
693501953	Sound study 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011263