

Fed 1-32  
API: 05-103-08074  
Inspection: 679706677




**Photo 1. Location.**



Fed 1-32  
API: 05-103-08074  
Inspection: 679706677



**Photo 2. Unused tank near gas meter pit.**



**Photo 3. Weeds in gas meter pit.**



**Fed 1-32**  
**API: 05-103-08074**  
**Inspection: 679706677**



**Photo 4. Unused tank near well head pit.**



**Photo 5. Vegetation in well head pit.**