

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402268319

Date Received:  
12/19/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 BROADWAY STE 2300

City: DENVER State: CO Zip: 80290

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Kyle Waggoner

4326616647

kyle.waggoner@whiting.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696200818

Inspection Date: 11/05/2019

FIR Submit Date: 11/19/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: WHITING OIL & GAS CORPORATION

Company Number: 96155

Address: 1700 BROADWAY STE 2300

City: DENVER State: CO Zip: 80290

### LOCATION - Location ID: 315169

Location Name: HILL-61N101W Number: 6NESW County: \_\_\_\_\_

Qtrqr: NESW Sec: 6 Twp: 1N Range: 101W Meridian: 6

Latitude: 40.083530 Longitude: -108.774160

### FACILITY - API Number: 05-103-00 Facility ID: 315169

Facility Name: HILL-61N101W Number: 6NESW

Qtrqr: NESW Sec: 6 Twp: 1N Range: 101W Meridian: 6

Latitude: 40.083530 Longitude: -108.774160

### CORRECTIVE ACTIONS:

1 ☒ CA# 134690

Corrective Action: Repair and maintain fence.

Date: 12/19/2019

Response: CA COMPLETED

Date of Completion: 12/18/2019

Operator  
Comment:

The fence has been repaired (see photo).

COGCC Decision: Approved

Photos provided show maintenance has been conducted on fence at access road.

COGCC  
Representative:

3 ☒ CA# 134692

Corrective Action: Comply with 1002.f

Date: 12/19/2019

Response: CA COMPLETED

Date of Completion: 12/18/2019

Operator  
Comment:

The road has been graded and erosion control BMPs have been installed (see photos).

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

It is unclear in the photos provided if sufficient site specific stormwater and erosion control BMPs have been installed in accordance with good engineering practices per Rule 1002.f. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kyle Waggoner

Signed: \_\_\_\_\_

Title: Field Regulatory Manager

Date: 12/19/2019 2:02:23 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402268319	FIR RESOLUTION SUBMITTED
402268328	Fence Repair
402268337	Culvert Removed
402268341	Erosion Control BMPs

Total Attach: 4 Files