

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402277856

Date Received:  
01/06/2020

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
-		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900742  
Inspection Date: 08/29/2019 FIR Submit Date: 09/09/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326128

Location Name: FRANK DAVIS GAS UNIT A Number: 3NWSE County: LA PLATA  
PLA-6-N33N10  
Qtrqr: NWSE Sec: 3 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.129792 Longitude: -107.919627

FACILITY - API Number: 05-067- -00 Facility ID: 215921

Facility Name: FRANK DAVIS A Number: 1  
Qtrqr: NWSE Sec: 3 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.129792 Longitude: -107.919627

CORRECTIVE ACTIIONS:

**1** CA# 130250

Corrective Action: Remove waste and debris. Date: 09/20/2019

Response: CA COMPLETED Date of Completion: 09/18/2019

Operator Comment: All trash and debris on location cleaned up see attached.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 130251

Corrective Action: Bare soils within the southeastern project area need revegetation and stabilization within the fall 2019 seeding window.

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 09/18/2019

Operator Comment: Bare areas seeded see attached.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 130252

Corrective Action: Stormwater erosion and sedimentation needs to be controlled within the project area. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control.

Date: 09/20/2019

Response: CA COMPLETED

Date of Completion: 09/18/2019

Operator Comment: Rebuilt berms and installed/maintained rock rundowns on location see attached photos of work completed.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 1/6/2020 11:23:07 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

402277863	Work completion photos
-----------	------------------------

Total Attach: 1 Files