

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2020

Submitted Date:

01/10/2020

Document Number:

690101656

FIELD INSPECTION FORMLoc ID 321612 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10713

Name of Operator: DARRAH OIL COMPANY LLC

Address: 125 N MARKET STE 1425

City: WICHITA State: KS Zip: 67202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Welsh, Brian		brian.welsh@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Atterbury, Mike	(316) 219-3390	mike.atterbury@darrahoil.com	
Darrah, Will		will.darrah@darrahoil.com	
Whittington, Ellice		ellice.whittington@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207511	WELL	PR	05/27/1984	OW	017-06446	CHAMPLIN 205 AMOCO 5	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection Only. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link(s) at end of report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pump Jack

1

Comment: [National 320](#)Corrective Action: Date:

Type: Prime Mover

#

Comment: [Electric Motor](#)Corrective Action: Date:

Type: Ancillary equipment

2

Comment: [Electric panel and cathodic rectifier](#)Corrective Action: Date:

Type: Deadman # & Marked

4

Comment: Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected FacilitiesFacility ID: 207511 Type: WELL API Number: 017-06446 Status: PR Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently producing.

The off location flowline (wellhead line) runs approximately 3045' SW from the wellhead to facility/ battery (shared facility/ battery servicing Champlin 205 Amoco A-2, A-4, A-5 wells @ 38.723500/-102.533240) on the north side of CR J. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Darrah Oil Company with off location flowlines.

Corrective Action: **Comply with the following COGCC rule (partial description):**

1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101657	Aerial	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033679
690101658	Signage at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033680
690101659	View South from wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033681