

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402275285

Date Received:

12/31/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jessica Dooling

970-675-4122

jessica_dooling@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699700062

Inspection Date: 11/20/2019

FIR Submit Date: 12/02/2019

FIR Status: _____

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 316373

Location Name: YELLOW CREEK FEDERAL-61S98W Number: 3NESE County: _____

Qtrqtr: NESE Sec: 3 Twp: 1S Range: 98W Meridian: 6

Latitude: 39.991140 Longitude: -108.370750

FACILITY - API Number: 05-103-00 Facility ID: 316373

Facility Name: YELLOW CREEK FEDERAL-61S98W Number: 3NESE

Qtrqtr: NESE Sec: 3 Twp: 1S Range: 98W Meridian: 6

Latitude: 39.991140 Longitude: -108.370750

CORRECTIVE ACTIONS:

1 ☒ CA# 134991

Corrective Action: Operator shall properly treat or dispose of the stockpiled soil in accordance with Rule 907.f and provide that information on an eForm 27 under Remediation 14580. Provide waste transportation and final disposition information in accordance with 907.b. (2) for all E&P waste transported off site. Berms on the northeast side of the larger stockpile are in disrepair.

Date: 01/02/2020

Response: CA COMPLETED

Date of Completion: 12/31/2019

Berm on NE side of pad repaired 12/29/2019, see attached photo.

Operator Comment: BAsed on 12/31/2019 email from John Heil, stockpiled materail will be removed once delination and remediation are completed, see REM# 14580. Removal of stockpiled material is pending approval to import fill material.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Berm on NE side of pad repaired 12/29/2019, see attached photo.

BAsed on 12/31/2019 email from John Heil, stockpiled materail will be removed once delination and remediation are completed, see REM# 14580. Removal of stockpiled material is pending approval to import fill material.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed: _____

Title: Regulatory Coordinator

Date: 12/31/2019 2:00:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402275285	FIR RESOLUTION SUBMITTED
402275300	20191229 Berm repaired photo
402275302	20191231 John Heil email

Total Attach: 3 Files