

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/16/2020

Submitted Date:

01/17/2020

Document Number:

679707013

FIELD INSPECTION FORM

Loc ID 316154 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 200502
Name of Operator: 31 OPERATING
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232248	WELL	PR	10/16/2003	GW	103-09919	ANT HILL UNIT 30-42	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 1-16-2020 at approximately 15:00, inspector Rick Moran, conducted a follow up inspection at 31 Operating well WRD Federal 30-42 in Rio Blanco county of FIR document 679706590.

The following compliance issues were resolved:
1) Missing "911" on battery sign.

The following compliance issues are uncompleted:
1) Stormwater channel at edge of location with sediment depositing off location. Photos 1 & 6. Complete by 1-17-2020.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679707013.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:	Container of methanol and 1 container of parafin solvent both with secondary containment.			Date:	
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		40.107920,-108.210150
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.107920,-108.210150
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 232248 Type: WELL API Number: 103-09919 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: [Stormwater channel at edge of location with sediment depositing off location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 01/17/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679707014	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5041191