

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 402297066			

**BRADENHEAD TEST REPORT**

Step 1. Record all tubing and casing pressures as found. Step 2. Sample now. If intermediate or surface casing pressure > 25 psi. In sensitive areas, 1 psi.  
Step 3. Conduct Bradenhead casing. Step 4. Conduct intermediate casing test. Step 5. Send report to BLM within 3 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: 65110 3. BLM Lease No: \_\_\_\_\_

2. Name of Operator: O'BRIEN ENERGY RESOURCES CORP

4. API Number: 05-123-23984-00 5. Multiple completion? ☐ Yes ☒ No

6. Well Name: LOST CREEK Number: 31

7. Location (QtrQtr, Sec, Twp, Rng, Meridian): NENE,21,3N,62W,6

8. County WELD 9. Field Name: PEACOCK

10. Minerals: ☒ Fee ☐ State ☐ Federal ☐ Indian

11. Date of Test: 01/28/2020

12. Well Status: ☐ Flowing  
☒ Shut In ☐ Gas Lift  
☐ Pumping ☐ Injection  
☐ Clock/Intermitter  
☐ Plunger Lift

13. Number of Casing Strings:  
☒ Two ☐ Three ☐ Liner?

**14. EXISTING PRESSURES**

Record all pressures as found	Tubing: _____	Tubing: _____	Prod Csg 953	Intermediate	Surf. Csg
	Fm: _____	Fm: _____	Fm: _____	Csg: _____	0

**BRADENHEAD TEST**

<p>Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals Define characteristics of flow in "Bradenhead Flow" column using letter designations below:  O = No Flow; C = Continuous; D = Down to 0; V = Vapor  H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas</p>	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
	00:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	O
	05:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	O
	10:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	O
	15:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	O
	20:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	O
	25:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	O
<p>BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid</p> <p>Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh  <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black</p> <p>Other:(describe) _____</p> <p>Sample cylinder number: _____</p>						
Instantaneous Bradenhead PSIG at end of test: > 0						

**INTERMEDIATE CASING TEST**

<p>Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals Characterize flow in "Intermediate Flow" column using letter designations below:  O = No Flow; C = Continuous; D = Down to 0; V = Vapor  H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas</p>	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
	00:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	05:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	10:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	15:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	20:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	25:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
<p>INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid</p> <p>Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh  <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black</p> <p>Other:(describe) _____</p> <p>Sample cylinder number: _____</p>						
Instantaneous Intermediate Casing PSIG at end of test: >						

Comments: No tubing in the hole. Monitored production casing during test. Good test, no pressure anomalies. Braden test valve piped to surface with 1" riser.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: Randy Walck Title: President Walck Consultin Phone: (970) 250-0586

Signed: JOSEPH FORMA Title: PRESIDENT Date: 1/29/2020

Witnessed By: Title: Agency: