

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402295959

Date Received:
01/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 1125 ESCALANTE DR

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kellerby, Shaun

970-712-1248

shaun.kellerby@state.co.us

Utah Gas Corp

720-425-0303

inspections@utahgascorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679703772

Inspection Date: 04/17/2019

FIR Submit Date: 04/18/2019

FIR Status: _____

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP

Company Number: 10539

Address: 1125 ESCALANTE DR

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 316020

Location Name: DRAGON TRAIL UNIT-62S102W Number: 21SWNW County: RIO BLANCO

Qtrqtr: SWN Sec: 21 Twp: 2S Range: 102W Meridian: 6
W

Latitude: 39.861507 Longitude: -108.856856

FACILITY - API Number: 05-103- -00 Facility ID: 231931

Facility Name: DRAGON TRAIL UNIT Number: 1150

Qtrqtr: SWN Sec: 21 Twp: 2S Range: 102W Meridian: 6
W

Latitude: 39.861507 Longitude: -108.856856

CORRECTIVE ACTIONS:

1 ☒ CA# 124393

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 03/08/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator Comment: Secondary containment repaired

COGCC Decision: Approved

COGCC Representative: Follow up inspection 679704113 on 5-17-2019.

2 ☒ CA# 124394

Corrective Action: Comply with Rule 603.f .

Date: 04/30/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator Comment: Debris removed

COGCC Decision: Approved

COGCC Representative: Follow up inspection 679704113 on 5-17-2019.

3 ☒ CA# 124395

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/20/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator Comment: Stormwater BMP repaired and soil scour repaired

COGCC Decision: Approved

COGCC Representative: Follow up inspection 679704113 on 5-17-2019.

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions were completed 5/7/19 and follow up inspection on 5/17/19 indicated CA's resolved

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Robert Bleil

Signed: _____

Title: Regulatory Manager

Date: 1/28/2020 9:52:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402295959	FIR RESOLUTION SUBMITTED
402295965	Photo of liner repaired
402296006	Follow up inspection #679704113 identifying CA's resolved

Total Attach: 3 Files