

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2020

Submitted Date:

01/30/2020

Document Number:

693502128**FIELD INSPECTION FORM**Loc ID 455317 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455315	WELL	DG	06/10/2019		014-20757	Livingston S19-25-14C	DG

General Comment:

Inspected Facilities

Facility ID: 455315 Type: WELL API Number: 014-20757 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 1-21-2020
 Complaint Contacted:
 Date: 1-30-2020 Time: 9:45AM phone
 Location ID # 455317
 Location name: Livingston
 Inspection Document # 693502121
 Complaint Document # 200448583
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 1-21-2020, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Courtney Weiss 3921 Wild Horse Dr Broomfield stated the issues were occurring outside of complainants home.
 On 1-21-2020, I attempted to make contact with the complainant who indicated that on 1-19-2020 experienced a constant rumbling noise. Noise sounds like train/jet engine.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual noise in or around location. After reviewing third party sound data submitted, it appears location is within COGCC rules. At time of inspection, it appears Extraction is installing additional sound walls on south side of location.
 At time of inspection, I spoke with frac supervisor he stated at time of complaint they were fracing and no unusual activity was taking place. This is Liberty Oilfield Services Tier 4 Quiet fleet.
 Weather conditions: Clear and location dry
 See inspection document #693502121 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See inspection doc#693502121 for full inspection. Third party sound data is attached to complaint inspection document.	silverr	01/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693502129	Sound data	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5052691