

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402256021

Date Received:
12/05/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Distribution, Evergreen</u>		<u>cogcc.evergreen@enrllc.com</u>
<u>Tom Beardslee</u>		<u>tom.beardslee@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695101333
Inspection Date: 09/12/2019 FIR Submit Date: 09/12/2019 FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307835

Location Name: COLOROW-634S65W Number: 24NENW County: LAS ANIMAS
Qtrqtr: NENW Sec: 24 Twp: 34S Range: 65W Meridian: 6
Latitude: 37.074700 Longitude: -104.624110

FACILITY - API Number: 05-071- -00 Facility ID: 257733

Facility Name: COLOROW Number: 21-24
Qtrqtr: NENW Sec: 24 Twp: 34S Range: 65W Meridian: 6
Latitude: 37.074700 Longitude: -104.624110

CORRECTIVE ACTION:

1 CA# 130536

Corrective Action: REMOVE UNUDED EQUIPMENT, COMPLY WITH RULE 603.f. Date: 10/12/2019

Response: CA COMPLETED Date of Completion: 09/13/2019

Operator Comment: Removed unused equipment to comply with Rule 603.f.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 130537

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 10/12/2019

Response: CA COMPLETED

Date of Completion: 09/13/2019

Operator Comment: Installed proper guy line markers per Rule 1003.a.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 CA# 130539

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 902.b.

Date: 10/12/2019

Response: CA COMPLETED

Date of Completion: 09/13/2019

Operator Comment: Lowered fluid level so at least two feet of freeboard exist, per Rule 902.b.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: No photos of the CA are available currently

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cheri Morgan

Signed: _____

Title: Regulatory Specialist

Date: 12/5/2019 6:24:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402256021	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files