

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402307153

Date Received:  
02/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901381

Inspection Date: 01/22/2020

FIR Submit Date: 01/27/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 311911

Location Name: HAHN-N33N8W Number: 15SESW County: LA PLATA

Qtrqr: SESW Sec: 15 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099840 Longitude: -107.708390

FACILITY - API Number: 05-067- -00 Facility ID: 290038

Facility Name: IGE Number: 135

Qtrqr: SESW Sec: 15 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099840 Longitude: -107.708390

CORRECTIVE ACTIONS:

1 CA# 136159

Corrective Action: Remove and properly dispose of Russian thistle debris.

Date: 02/14/2020

Response: CA COMPLETED

Date of Completion: 02/06/2020

Operator Comment: Removed Russian Thistle debris.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 136160

Corrective Action: Remove and properly store unused equipment.

Date: 02/28/2020

Response: CA COMPLETED

Date of Completion: 02/06/2020

Operator  
Comment: Removed unused equipment.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 136161

Corrective Action: Stormwater and erosion controls are needed to stabilize bare soils within the project area.

Date: 02/28/2020

Response: CA COMPLETED

Date of Completion: 02/06/2020

Operator  
Comment: Installed erosion logs, seeded and applied straw mulch on bare slope.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: \_\_\_\_\_

Title: Geo/Eng Tech

Date: 2/10/2020 7:25:29 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402307156	Remedial Report
-----------	-----------------

Total Attach: 1 Files