

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402308258

Date Received:
02/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>James, Brian</u>		<u>bjames@hpres.com</u>
<u>Kraich, Adam</u>		<u>adam.kraich@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696301245
Inspection Date: 02/06/2020 FIR Submit Date: 02/06/2020 FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 421665

Location Name: Anschutz State 5-62-27_34 Number: SESE 22 County: _____
Qtrqtr: SESE Sec: 22 Twp: 5N Range: 62W Meridian: 6
Latitude: 40.379067 Longitude: -104.301525

FACILITY - API Number: 05-123-00 Facility ID: 421665

Facility Name: Anschutz State 5-62-27_34 Number: SESE 22
Qtrqtr: SESE Sec: 22 Twp: 5N Range: 62W Meridian: 6
Latitude: 40.379067 Longitude: -104.301525

CORRECTIVE ACTIONS:

1 CA# 136389

Corrective Action: Comply with Rule 603.f. Date: 03/06/2020

Response: CA COMPLETED Date of Completion: 02/10/2020

Operator Comment: unused seperator has been removed

COGCC Decision: _____

unused culverts have been removed

--

unuses wellhead parts at Windmill 4-22H have been removed.

Date: 2/10/2020 2:41:44 PM

Page 2 of 2