

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402062101

Date Received:
06/12/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
		<u>sandridgeenvironmental@sandridgeenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400966
Inspection Date: 05/08/2019 FIR Submit Date: 05/16/2019 FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC Company Number: 10598
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 446527

Location Name: Pintail Number: 16 County: _____
Qtrqr: NESW Sec: 16 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.573971 Longitude: -106.382214

FACILITY - API Number: 05-057-00 Facility ID: 446527

Facility Name: Pintail Number: 16
Qtrqr: NESW Sec: 16 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.573971 Longitude: -106.382214

CORRECTIVE ACTIONS:

1 CA# 125205

Corrective Action: Remove unused equipment from site. Date: 04/06/2019

Response: CA COMPLETED Date of Completion: 05/10/2019

Operator Comment: Equipment was removed from site.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 125206

Corrective Action: Reclaim Location for Interim Reclamation per COGCC 1003 Series Rules; installing Reclamation in areas no longer needed for Use, Production, Drilling or Subsequent Operations.

Date: 06/14/2019

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator Comment: SD submitted an amended Form 2A showing the equipment and area of the pad that will be used for field operations. Please see attached plat.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Form 4 has been submitted reporting that Interim reclamation has commenced as of 11/4/19.

3 CA# 125207

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/14/2019

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator Comment: Rilling was repaired and area reseeded and mulched. Straw wattles were placed over repaired area.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Church

Signed: _____

Title: EH&S Specialist

Date: 6/12/2019 7:39:41 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402062101	FIR RESOLUTION SUBMITTED
402071889	Pintail Plat

Total Attach: 2 Files