

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402295035

Date Received:
01/27/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Edie, Fitzgerald</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102088
Inspection Date: 01/22/2020 FIR Submit Date: 01/24/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308798

Location Name: GOLDEN EAGLE-633S67W Number: 30SESW County: LAS ANIMAS
Qtrqtr: SESW Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.136682 Longitude: -104.931920

FACILITY - API Number: 05-071-00 Facility ID: 282122

Facility Name: GOLDEN EAGLE Number: 30-14
Qtrqtr: SESW Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.136682 Longitude: -104.931920

CORRECTIVE ACTIONS:

1 CA# 136109

Corrective Action: CLEAN COMPRESSOR AND REPAIR LEAKS (TO PREVENT FUTURE SOIL CONTAMINATION), Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 02/23/2020

Response: CA COMPLETED

Date of Completion: 01/27/2020

Operator Comment: All fittings were securely fastened.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 136110

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 01/28/2020

Response: CA COMPLETED Date of Completion: 01/27/2020

Operator Comment: All leaks were repaired, the stains on the ground were removed. The Senior Production Foreman has reviewed the self inspection process.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 CA# 136111

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 01/28/2020

Response: CA COMPLETED Date of Completion: 01/27/2020

Operator Comment: The liquid ring compressor skid and reservoir was cleaned. The oil/fluid accumulation was removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4 CA# 136112

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection.

Date: 01/28/2020

Response: CA COMPLETED Date of Completion: 01/27/2020

Operator Comment: The liquid ring compressor skid and reservoir was cleaned. The oil/fluid accumulation was removed from the reservoir. The impacted soil on the ground was removed. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 1/27/2020 11:40:02 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402295035	FIR RESOLUTION SUBMITTED
402295092	Photo Log

Total Attach: 2 Files