

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	oil leaking from wellhead		
Corrective Action:	Comply with Rule 605.d	Date:	11/14/2019
Type	OTHER		
Comment:	oil spill at wellhead and outside of containment appears to be less than 1 bbl		
Corrective Action:	Comply with Rule 907.e	Date:	11/15/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, transformers and meter box		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241023 Type: WELL API Number: 123-08811 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 2/6/2020 at approximately 1615 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Nessu-2 at API #05-123-08811 in Weld County Colorado.</p> <p>While there, I observed a SI wellsite. This is a follow up inspection per Doc. # 697600583 During this inspection the following possible compliance issues were observed and are delinquent: 605.d Housekeeping: Mechanical issue WH leaking crude oil CA date 11/14/2019. 907.e Housekeeping: Oil spill at WH CA date 11/15/2019 see attached photos. I spoke with Hannah at the KP Kauffman office at 1620 hrs and told her about the leak and she forwarded me on to the KP Kauffman landman and i left a voice mail stating that the wellhead has a leak and stained the soil. Location is partially snow covered, weather is overcast and cold. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	02/06/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402306220	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060181
699301052	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060174