

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402123134

Date Received:

07/26/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Church, Matt

405-651-6853

mchurch@sandridgeenergy.com

sandridgeenvironmental@sandridgeenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692401153

Inspection Date: 06/27/2019

FIR Submit Date: 07/19/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC

Company Number: 10598

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 447512

Location Name: Open Range Number: 18 County: _____

Qtrqtr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

FACILITY - API Number: 05-057-00 Facility ID: 447512

Facility Name: Open Range Number: 18

Qtrqtr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

CORRECTIVE ACTIONS:

1 ☒ CA# 128295

Corrective Action: Comply with Rule 603.f.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/22/2019

Operator Comment: Supplies removed from site and stored in trailer.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 128296

Corrective Action: Comply with Rule 603.f .

Date: _____

Response: CA COMPLETED

Date of Completion: 07/23/2019

Operator
Comment: Crews directed to clean site and site was cleaned with all trash and debris removed and placed in dumpster.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 128297

Corrective Action: Remove Soil Material stockpiles from Location.

Date: 05/29/2019

Response: CA COMPLETED

Date of Completion: 07/26/2019

Operator
Comment: Stockpile of soil was from trenching operations. The material contains wood, pieces of pallet, liner, and general debris. The material is being hauled to disposal at a licensed landfill located in Milner, CO - Twin Enviro. The material will have manifests tracking its disposal.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 128298

Corrective Action: Install sufficient/effective BMPs in accordance with, and monitoring per Good Engineering Practices per Rule 1002.f Exclude traffic from West auxiliary portion of site until area & road are stabilized & BMPs repaired / installed. Refer to Photo Log attached & aerial with area of concern attached.

Date: 06/14/2019

Response: CA COMPLETED

Date of Completion: 07/25/2019

Operator
Comment: West auxiliary road and BMPs around site are being repaired, a Form 42 for this work on 7/25 and a sundry form 4 will be filed on 7/26.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Church

Signed: _____

Title: EHS Specialist

Date: 7/26/2019 7:53:59 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402123134	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files