

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

679602268**FIELD INSPECTION FORM**Loc ID 332990 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285790	WELL	PA	12/19/2018	OW	123-24036	CHRISTIANSEN 35-13	PA
286564	WELL	PR	02/01/2019	GW	123-24230	CHRISTIANSEN 35-15	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No sign at tank battery. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/06/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused risers near separators. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	03/06/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		40.444400,-104.855200	
Comment:	Anchored (in floodplains)					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 285790 Type: WELL API Number: 123-24036 Status: PA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: SITE CONDITIONComment: PA FORM 6(S): 401901235 in well file.Corrective Action: Date: Facility ID: 286564 Type: WELL API Number: 123-24230 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: TANK BATTERY CONNECTEDComment: SI; pilot offCorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>**Weather Conditions: cloudy, snow on ground</p> <p>On Thursday, February 6, 2020 at approximately 13:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at CHRISTENSEN 35-13, 35-15 (PDC Energy), at location #: 332990 in WELD COUNTY Colorado.</p> <p>While there, I observed a shut in wellhead/facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. No sign installed at tank battery. INSTALL SIGN TO COMPLY WITH RULE 210.B. (Corrective Action Date: March 6, 2020) See attached photo #4.</p> <p>2. Unused risers near separator. LO/TO WITHIN 24HRS; IF NO PLAN FOR FUTURE USE, REMOVE AND COMPLY WITH RULE 603.F. (Corrective Action Date: March 6, 2020) See attached photos #5,6</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	02/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402306349	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060321
679602270	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060319