

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402315227

Date Received:  
02/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>BAKER DAVID</u>		<u>dbaker@auroramp.com</u>
<u>Edie Fitzgerald</u>		<u>ediefitzgerald@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901721  
Inspection Date: 01/30/2020 FIR Submit Date: 01/31/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309119

Location Name: GOLDEN EAGLE-633S67W Number: 31NWNE County: LAS ANIMAS  
Qtrqr: NWNE Sec: 31 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.133790 Longitude: -104.926200

FACILITY - API Number: 05-071-00 Facility ID: 288302

Facility Name: GOLDEN EAGLE Number: 31-2  
Qtrqr: NWNE Sec: 31 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.133790 Longitude: -104.926200

CORRECTIVE ACTIIONS:

1 CA# 136251

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area. 5 days to implement improved procedures.

Date: 02/05/2020

Response: CA COMPLETED

Date of Completion: 02/05/2020

Operator Comment: The oily waste was removed from the PC skid. The impacted soil near the liquid ring, tank and separator was cleaned up removed from location immediately. Non-structural BMP's were implemented for improved material handling. The field employees attended a training regarding improved material handling techniques.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: SR. Environmental Tech.

Date: 2/18/2020 11:05:37 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files