

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402079949

Date Received:
06/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		SanJuanCOGCC@bp.com sabre.beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900331
Inspection Date: 05/17/2019 FIR Submit Date: 05/22/2019 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306763

Location Name: MCCA W W A T E R D I S P O S A L - M 3 4 N 8 W Number: 20NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 20 Twp: 34N Range: 8W Meridian: M
Latitude: 37.175339 Longitude: -107.737354

FACILITY - API Number: 05-067-00 Facility ID: 263422

Facility Name: MCCA W W A T E R D I S P O S A L (EPA) Number: 2
Qtrqtr: NWSE Sec: 20 Twp: 34N Range: 8W Meridian: M
Latitude: 37.175339 Longitude: -107.737354

CORRECTIVE ACTIIONS:

1 CA# 125393

Corrective Action: Conduct interim reclamation within the project area. Date: 06/28/2019

Response: CA COMPLETED Date of Completion: 06/11/2019

Operator Comment: Reseeding of interim reclamation along with storm water BMP installation performed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative]

2 CA# 125394

Corrective Action: Stormwater controls designed to stabilize erosion and sediment are needed while interim reclamation ins conducted, and until location is stabilized with perennial vegetation. Stormwater controls need to be selected, sized, and installed in accordance with good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 06/11/2019

Operator Comment: diversion ditch installed with armoring for stormwater management. hydroseeding conducted to attempt to reestablish vegetation again.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative]

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions complete

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/19/2019 6:23:25 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402079949	FIR RESOLUTION SUBMITTED
402079950	completion document

Total Attach: 2 Files