

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2020

Submitted Date:

03/03/2020

Document Number:

693200573

FIELD INSPECTION FORM

Loc ID 322352 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
 Address: 5057 KELLER SPRINGS RD STE 650
 City: ADDISON State: TX Zip: 75001

Findings:

3 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Contact, General		regulatory@foundationenergy.com	Regulatory
McFarland, Nick		nick.mcfarland@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210347	WELL	SI	08/04/2009	GW	045-06103	FEDERAL 23-12	PA

General Comment:

Engineering Integrity Inspection performed on February 27, 2020. In response to Form 6 Document number 401846973

COGCC staff met with foundation staff on location to discuss flowlines. Foundation staff stated that gas sales changed custody at wellhead and that the flowline belongs to Excel Energy, and flowline was abandoned by Excel Energy. Foundation field staff stated that flowline was removed before he and workover rig moved onto location.

Photo log attached, picture of weld on maker below grade and picture with cement to surface, with no flowline in field of vision.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200574	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5084604