

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402334721

Date Received:
03/06/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------------------------|-------|-----------------------------------|
| <u>Tom Beardslee</u> | | <u>tom.beardslee@state.co.us</u> |
| <u>Distribution, Evergreen</u> | | <u>cogcc.evergreen@enrllc.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 695100651
Inspection Date: 05/20/2019 FIR Submit Date: 05/20/2019 FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333464

Location Name: KEIKO-633S66W Number: 6SESW County: LAS ANIMAS
Qtrqtr: SESW Sec: 6 Twp: 33S Range: 66W Meridian: 6
Latitude: 37.194270 Longitude: -104.825630

FACILITY - API Number: 05-071-00 Facility ID: 273233

Facility Name: KEIKO Number: 14-6
Qtrqtr: SESW Sec: 6 Twp: 33S Range: 66W Meridian: 6
Latitude: 37.194270 Longitude: -104.825630

CORRECTIVE ACTION:

1 CA# 125531

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605. CA FROM PREVIOUS INSPECTION DOC #687902080

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 07/30/2018

Operator Comment: Corrective action is complete photos attached.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 125532

Corrective Action: Install sign to comply with Rule 210.d.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 03/04/2020

Operator Comment: Corrective action is complete photos attached.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 125533

Corrective Action: Pioneer needs to investigate and possibly correct the Lease sign on the Keiko 14-6 TR (05-071-8629) well to SESW. Contact (COGCC)Dennis Ahlstrand : 303-894-2100, xt 5116 of any changes. CA FROM LAST INSPECTION NOT ADDRESSED DOC #687902080

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 07/30/2018

Operator Comment: Corrective action is complete photos attached.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action is complete photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cheri Morgan

Signed: _____

Title: Reg. Specialist

Date: 3/6/2020 10:21:48 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|-------|
| 402334750 | Photo |
|-----------|-------|

Total Attach: 1 Files