

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402242662

Date Received:  
12/03/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ferrin, Jeremy</u>		<u>jeremy.ferrin@state.co.us</u>
<u>Arthur, Denise</u>		<u>denise.arthur@state.co.us</u>
<u>Axelson, John</u>		<u>john.axelson@state.co.us</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Javernick, James</u>	<u>719-275-3040/719-671-3787</u>	<u>javernick1@gmail.com</u>
<u>Costa, Ryan</u>		<u>ryan.costa@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900047

Inspection Date: 02/28/2019

FIR Submit Date: 03/11/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

LOCATION - Location ID: 322215

Location Name: TEMPLETON-620S69W Number: 4NWSE County: FREMONT

Qtrqtr: NWSE Sec: 4 Twp: 20S Range: 69W Meridian: 6

Latitude: 38.334670 Longitude: -105.111310

FACILITY - API Number: 05-043-00 Facility ID: 209871

Facility Name: TEMPLETON Number: 1

Qtrqtr: NWSE Sec: 4 Twp: 20S Range: 69W Meridian: 6

Latitude: 38.334670 Longitude: -105.111310

CORRECTIVE ACTIONS:

1  CA# 123119

Corrective Action:

Date: 03/12/2019

Remove free fluids and contact COGCC EPS staff, Jason Kasola, per Rule 906.b, within 24 hours of receipt of this inspection. (719) 574-8602 (office) or (719) 641-0291 (cell)

Response: CA COMPLETED

Date of Completion: 03/13/2019

Operator Comment: Inspected well head and removed free fluid from area.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**2**  CA# 123120

Corrective Action: Remove waste and debris.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/19/2019

Operator Comment: Removed scattered wood and other debris within the project area.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**3**  CA# 123121

Corrective Action: Stabilization measures and stormwater controls need to be installed immediately to stabilize the bank of the erosional channel from eroding any further and manage stormwater erosion within the project area. This needs to be an engineered long-term solution sufficient to stabilize the cut-bank, and address run-on and runoff issues with properly sized and installed stormwater and erosion controls.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/19/2019

Operator Comment: Channel filled with rip-rap and soil to rebuild and restabilize the cut-bank and address run-on and runoff issues.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: James Javernick

Signed: \_\_\_\_\_

Title: Owner

Date: 12/3/2019 2:20:01 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402242662	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files