



Comment:

The bottom of the completed interval is at 594 'FNL and 523' FWL of Section 11.  
During stimulation the wellbore was isolated by a composite bridge plug set at 17717'.  
Great Western certifies that none of the wellbore beyond the unit boundary setback was completed.

Great Western certifies that this well has no treated interval within 150' of the treated interval of another operator's well for which a signed Stimulation Setback Consent was not obtained. The Ehrlich-PM O 12-1 (API # 123-14116) and Bernhardt-PM O 12-03 (API # 123-14047) were P&A'ed prior to treating the Schneider HD 11-022HN.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Eileen Roberts  
Title: Regulatory Analyst Date: \_\_\_\_\_ Email: eroberts@gwp.com  
:

### Attachment Check List

Att Doc Num      Name

--	--

Total Attach: 0 Files

### General Comments

User Group      Comment      Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)