

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2020

Submitted Date:

03/30/2020

Document Number:

699101315

FIELD INSPECTION FORMLoc ID 306544 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------------------------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 289577 | WELL | SI | 01/01/2019 | GW | 123-24880 | BECKER 8-12I | SI |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Sign missing/ not posted at well. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 04/30/2020 |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----------------------------------|-------|-----------------|
| Type: Bird Protectors | # 2 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface. | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |

| | | | |
|--------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|----------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | , | |
| Comment: | Shares containment with crude oil tank. | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.257460,-104.581090 |
| Comment: | | | | | |
| Corrective Action: | | | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | |

Flaring:

| | | |
|------|--|--|
| Type | | |
|------|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 289577 Type: WELL API Number: 123-24880 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Monday 3/30/20 at approximately 0816 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Becker 8-12I of PDC Energy, at Location ID: 306544 in Weld County, Colorado.

During this inspection the following possible compliance issues were observed:

Sign missing/ not posted at well. Install sign to comply with Rule 210.b. With a corrective action date of 4/30/20.

See attached photos.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Continuing education inspections

burnsa

03/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699101316 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5109686 |