



04/02/2020

WILLIAM BOYD LAND & REGULATORY MANAGER
RED HAWK PETROLEUM LLC
ATTN: WILLIAM BOYD
1250 WOOD BRANCH PARK STE 400
HOUSTON TX 77079

Dear Mr. Boyd,

RED HAWK PETROLEUM LLC is receiving this letter because, based on COGCC records, the COGCC has reason to believe that in addition to the well on the Warning Letter, more wells present one or more compliance issues as well. The wells listed below are all included on the Warning Letter and must be compliant by the Corrective Action date provided on that document.

Please do not hesitate to contact me with any questions regarding these compliance issues, or if these wells were incorrectly identified.

1. 123-33692 Marconi 1-1H
2. 123-34144 Planck 1-14H
3. 123-34161 Staudinger 1-31H
4. 123-34199 Hahn 1-4H
5. 123-34205 Perrin 1-10H
6. 123-34697 Dunn 1-13H
7. 123-34825 Buchner 1-2H
8. 123-34880 Reines 1-1H
9. 123-35277 Leggett 1-5H
10. 123-35357 Ford Family Trust 2H
11. 123-36243 Waves 1H
12. 123-36316 LOGAN 2H
13. 123-36703 Buchner 2-2H
14. 123-36841 Wallach 1-8H
15. 123-39927 Loomis 2-3H
16. 123-39929 Loomis 2-6H
17. 123-39930 Loomis 2-1H

Sincerely,

Ted Dinku
Engineering Technician





COLORADO
**Oil & Gas Conservation
Commission**
Department of Natural Resources

P 303.894.2100 x5144
1120 Lincoln Street, Suite 801, Denver, CO 80203
Ted.Dinku@state.co.us | www.colorado.gov/cogcc