

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402360981

Date Received:
04/02/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Whittington, Ellice</u>		<u>ellice.whittington@state.co.us</u>
<u>Deranleau, Greg</u>		<u>greg.deranleau@state.co.us</u>
<u>Baca, Matthew</u>		<u>matthew.baca@bpx.com</u>
<u>Murray, Richard</u>		<u>g.richard.murray@state.co.us</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Schlagenhauf, Mark</u>		<u>mark.schlagenhauf@state.co.us</u>
<u>Hughes, Jim</u>		<u>jimo.hughes@state.co.us</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690100899

Inspection Date: 11/09/2018

FIR Submit Date: 11/16/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.103723 Longitude: -107.897424

FACILITY - API Number: 05-067- -00 Facility ID: 458834

Facility Name: Thomas Jacquez E1 PW Line Number: _____

Qtrqr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.103723 Longitude: -107.897424

CORRECTIVE ACTIONS:1  CA# 120493

Corrective Action: Provide information outlined below in writing to COGCC Engineering Integrity Group for review (pertaining to compliance of COGCC series 1100 flowline regulations):

- 1) Final determination of root cause of failure(s) resulting in this release
- 2) Detailed description of all flowline repairs and/ or replacement work completed
- 3) Measures taken to prevent failure(s) from reoccurring at this location
- 4) Description of method(s) used to determine the extent/ endpoint of damage (downslope) along this flowline
- 5) Summary of all available historical monitoring data (integrity/ leak detection) for this section of flowline (SCADA, Pressure testing, etc.)
- 6) General assessment of the current integrity condition of all fiberglass pipe in service across the BP field
- 7) Measures taken to identify similar (high risk) areas across BP field where fiberglass flowline failures may occur
- 8) Conduct flowline pressure testing (post repair/ integrity confirmation) prior to returning this PW flowline to service.
- 9) Provide Integrity confirmation data (pressure testing charts/ data) to COGCC staff

Date: 01/16/2019

Response: CA COMPLETED

Date of Completion: 01/16/2020

Operator
Comment:

All actions completed via Administrative Order of Consent Docket No. 190400264

COGCC Decision: Approved

COGCC
Representative:

Corrective Actions outlined on FIR DOC #690100899 have been completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: All actions completed refer to docket no. 190400264

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 4/2/2020 5:51:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402360981	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files