

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402374577

Date Received:

04/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Rowley, Darren		drowley@logosresourcesllc.com
Sessions, Tamra		tsessions@logosresourcesllc.com
Marie Florez	505-787-2218	mflorez@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901332

Inspection Date: 01/09/2020

FIR Submit Date: 01/14/2020

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 326449

Location Name: IGNACIO 33-8-N33N8W Number: 12NWNE County: LA PLATA

Qtrqtr: NWNE Sec: 12 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122980 Longitude: -107.663920

FACILITY - API Number: 05-067-00 Facility ID: 216513

Facility Name: IGNACIO 33-8 Number: 001C

Qtrqtr: NWNE Sec: 12 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122980 Longitude: -107.663920

CORRECTIVE ACTIONS:

1 CA# 135935

Corrective Action: Remove and properly dispose of Russian thistle debris.

Date: 01/31/2020

Response: CA COMPLETED

Date of Completion: 01/28/2020

Operator Comment: In regard to COGCC document #693901332, The Russian thistle debris on the Ignacio 33-8#1C was properly disposed of on 1/28/2020.

COGCC Decision: _____

COGCC
Representative:

2 CA# 135936

Corrective Action: Conduct interim reclamation according to COGCC 1003 reclamation rules. This includes recontouring, decompaction, and revegetation of areas not needed for production operations. Reclamation needs to be conducted by May 1, 2020. Livestock exclusion and mulching will likely be needed for successful revegetation. Additional detail provided in attached photos.

Date: 06/30/2018

Weeds need to be controlled with subsequent monitoring and treatment as needed. Corrective action is back-dated as subsequent monitoring and treatment is not sufficiently conducted.

Response: CA COMPLETED

Date of Completion: 03/18/2020

Operator
Comment:

A contractor working For LOGOS Operating performed interim reclamation work to comply with the COGCC 1003 reclamation rules on March 18, 2020. This included installing storm water BMP's, recontouring, decompacting, and revegetating the areas not needed for production operations. The location was mulched to assist with successful revegetation. Additional detail provided in attached photos. Consistent with LOGOS Operating's policy noxious weeds will continue to be sprayed annually and more often as needed. We will work with our weed spraying vendor to ensure that the areas in question are adequately sprayed and monitored in the spring of 2020 and going forward.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tamra Sessions

Signed: _____

Title: Regulatory Specialist

Date: 4/17/2020 4:00:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402374579	Seeding/Straw
402374580	Seeding/Straw
402374581	Seeding/Straw
402374583	Seeding/Straw
402374589	Seeding/Straw
402374591	Seed Mix
402374592	Seed Mix Vendor

Total Attach: 7 Files